LIGHT LABORATORY INC.
8165 E Kaiser Blvd. Anaheim, CA 92808
www.lightlaboratory.com

NVLAP TESTING
NVLAP LAB CODE 200927-0

Report No: L082312002

Issue Date: 8/18/2023
Reference:N/A
Amendment:N/A

Report Prepared For: FX Luminaire / Lumascape
1940 Diamond Street San Marcos, CA 92078

Model Number: EA51ECO20WFLBC

Test: Photometric/Colorimetric/Electrical Test

Standards Used: Appropriate part or all test guidelines were used for test performed:

IESNA LM79: 2019 Approved Methods for Electrical and Photometric Measurements of Solid-State Lighting Products

ANSI NEMA ANSLG C78.377: 2017 Specification of the Chromaticity of Solid State Lighting Products

ANSI C82.77-10:2014: Harmonic Emission Limits-Related Quality Requirements for Lighting Equipment

Description of Sample: Client submitted the sample. Received in working and undamaged condition. No modifications were necessary.

Special Test Condition: Fixture is tested with no special conditions.

Date of Tests: 8/17/23

Seasoning of Sample: No seasoning was performed in accordance with IESNA LM-79.

Equipment List

Equipment Used	Model No	Stock No	Calibration Due Date
Chroma Programmable AC Source	61604	PS-AC02	--
Yokogawa Digital Power Meter	WT210	MT-EL06-S4	4/7/25
HP Power Supply	6032A	PS-DC05-S2	--
Fluke Digital Thermometer	52K/J	MT-TP05	5/24/25
LLI Type C Goniophotometer System	RMG-C-MKII	CD-LL04-GC	--
LLI 2M Sphere	2MR97	CD-SN03-S2	--
LLI Spectroradiometer	SPR-3000	MT-SC01-S2	Before Use

LIGHT LABORATORY INC.
8165 E Kaiser Blvd. Anaheim, CA 92808
www.lightlaboratory.com

NVLAP TESTING
NVLAP LAB CODE 200927-0

General Information	
Manufacturer:	FX Luminaire / Lumascape
Model Number:	EA51ECO20WFLBC
Driver Model Number:	CUSTOM

Test Summary	
Total Lumens:	212.00
Efficacy:	67.27
Color Redering Index:	81.9
Correlated Color Temperature:	2719
Input Voltage (VAC):	12.00
Input Current (Amp):	0.2829
Input Power (W):	3.15
Input Power Factor:	0.9283
Current ATHD (%):	35.9%

Test Condition	
Ambient Temperature (°C):	25.0
Stabilization Time (Hours):	1:20
Total Operating Time (Hours):	2:00





FIG. 1 LUMINAIRE

LIGHT LABORATORY INC.
8165 E Kaiser Blvd. Anaheim, CA 92808
www.lightlaboratory.com

Report No: L082312002
NVLAP TESTING
NVLAP LAB CODE 200927-0

Colorimetry Test Results




CRI & CCT

x	0.4604
y	0.4139
u'	0.2614
v'	0.5287
CRI	81.90
CCT	2719
Duv	0.00117

R Values

R1	79.72
R2	88.88
R3	97.17
R4	80.94
R5	79.82
R6	87.11
R7	83.17
R8	58.44
R9	7.75
R10	75.01
R11	80.11
R12	71.33
R13	81.46
R14	98.21
R15	72.24



LIGHT LABORATORY INC.
8165 E Kaiser Blvd. Anaheim, CA 92808
www.lightlaboratory.com

NVLAP TESTING
NVLAP LAB CODE 200927-0

Test Methods

Photometric Measurements - Goniophotometer

A Custom Light Laboratory Type C Rotating Mirror Goniophotometer was used to measure candelas(intensity) at each angle of distribution as defined by IESNA for the appropriate fixture type.

Ambient temperature is set to 25°C and is measured from the center of the fixture, within 1ft from the outside of the fixture. Temperature is maintained at 25°C throughout the testing process and the sample is stabilized for at least 30mins and longer as necessary for the sample to achieve stabilization.

Electrical measurements are measured using the listed equipment.

Spectral Measurements - Integrating Sphere

A Sensing Spectroradiometer SPR-3000, in conjunction with Light Laboratory 2 meter integrating sphere was used to measure chromaticity coordinates, correlated color temperature(CCT) and the color rendering index(CRI) for each sample.

Ambient temperature is set to 25°C and is measured from the center of the fixture, within 1ft from the outside of the fixture. Temperature is maintained at 25°C throughout the testing process and the sample is stabilized for at least 30mins and longer as necessary for the sample to achieve stabilization.

Electrical measurements are measured using the listed equipment.

Disclaimers:

The results related only to the samples as received and tested. This report must not be used by the customer to claim product certification, approval or endorsement by NVLAP, NIST or any agency of the Federal Government.

Report Prepared by : JG

Test Report Reviewed by:

Steve Kang
Quality Assurance

**Attached are photometric data reports.*

LIGHT LABORATORY INC.
8165 E. Kaiser Blvd. Anaheim, CA 92808
www.lightlaboratory.com

Photometric Test Report

IES FLOOD REPORT
PHOTOMETRIC FILENAME : L082312002.IES

DESCRIPTIVE INFORMATION (From Photometric File)

IESNA:LM-63-2002
[TEST] L082312002
[TESTLAB] LIGHT LABORATORY, INC. (www.lightlaboratory.com)
[ISSUEDATE] 8/18/2023
[MANUFAC] FX Luminaire / Lumascape
[LUMCAT] EA51ECO20WFLBC
[LUMINAIRE] Spot 20W MR16 2700K Flood Black Composite
[BALLASTCAT] CUSTOM
[OTHER] INDICATING THE CANDELA VALUES ARE ABSOLUTE AND
[MORE] SHOULD NOT BE FACTORED FOR DIFFERENT LAMP RATINGS.
[INPUT] 12 VAC
[TEST PROCEDURE] IESNA:LM-79-19

Note: Candela values converted from Type-C to Type-B

CHARACTERISTICS

NEMA Type	4 H x 4 V
Maximum Candela	669
Maximum Candela Angle	0H -7V
Horizontal Beam Angle (50%)	26.7
Vertical Beam Angle (50%)	27.1
Horizontal Field Angle (10%)	56.4
Vertical Field Angle (10%)	53.1
Lumens Per Lamp	N.A. (absolute)
Total Lamp Lumens	N.A. (absolute)
Beam Lumens	82
Beam Efficiency	N.A.
Field Lumens	164
Field Efficiency	N.A.
Spill Lumens	48
Luminaire Lumens	212
Total Efficiency	N.A.
Total Luminaire Watts	3.15
Ballast Factor	1.00

Photometric Toolbox (R) Copyright 2002-2019 by Lighting Analysts, Inc.
Calculations based on published IES Methods and recommendations, values rounded for display purposes.
Results derived from content of manufacturers photometric file.

IES FLOOD REPORT
PHOTOMETRIC FILENAME : L082312002.IES


AXIAL CANDELA

DEG.	HOR.	DEG.	VERT.
90	1	90	1
85	1	85	1
75	1	75	1
65	1	65	1
55	3	55	1
47.5	8	47.5	1
42.5	15	42.5	1
37.5	28	37.5	2
33	43	33	5
29	60	29	21
25.5	80	25.5	36
22.5	108	22.5	48
19.5	152	19.5	66
17	202	17	95
15	250	15	126
13	305	13	162
11	363	11	214
9	422	9	273
7	480	7	348
5	518	5	409
3	548	3	474
1	566	1	532
0	568	0	568
-1	566	-1	598
-3	548	-3	633
-5	518	-5	658
-7	480	-7	669
-9	422	-9	661
-11	363	-11	635
-13	305	-13	594
-15	250	-15	524
-17	202	-17	448
-19.5	152	-19.5	344
-22.5	108	-22.5	234
-25.5	80	-25.5	157
-29	60	-29	104
-33	43	-33	70
-37.5	28	-37.5	50
-42.5	15	-42.5	37
-47.5	8	-47.5	27
-55	3	-55	15
-65	1	-65	6
-75	1	-75	2
-85	1	-85	1
-90	1	-90	1

Photometric Toolbox (R) Copyright 2002-2019 by Lighting Analysts, Inc.
Calculations based on published IES Methods and recommendations, values rounded for display purposes.
Results derived from content of manufacturers photometric file.

IES FLOOD REPORT
PHOTOMETRIC FILENAME : L082312002.IES

AXIAL CANDELA DISPLAY




Maximum Candela = 669 Located At Horizontal Angle = 0, Vertical Angle =-7
H - Horizontal Axial Candela
V - Vertical Axial Candela

Photometric Toolbox (R) Copyright 2002-2019 by Lighting Analysts, Inc.
Calculations based on published IES Methods and recommendations, values rounded for display purposes.
Results derived from content of manufacturers photometric file.

IES FLOOD REPORT
PHOTOMETRIC FILENAME : L082312002.IES

ISOCANDELA CURVES



Maximum Candela = 669 Located At Horizontal Angle = 0, Vertical Angle =-7
50% Maximum Candela = 334.5
10% Maximum Candela = 66.9

Photometric Toolbox (R) Copyright 2002-2019 by Lighting Analysts, Inc.
Calculations based on published IES Methods and recommendations, values rounded for display purposes.
Results derived from content of manufacturers photometric file.